Version: 2022

Michael Hübner
Robert-Bosch-Str. 29
73550 Waldstetten
Deutschland

Internet: www.schiraumtechnik.com
E-Mail: info@schiraumtechnik.de

Telefon: +49 7171 49 59 836
Telefax: +49 7171 49 59 837

Operating manual for boot dryer “Trend”

Function
This wall fixable boot drying system is equipped with heating elements. Ski shoes, runners, walking boot etc. can be put on it for drying and warming.

Heating temperature
Heating temperature is below 50°C, so the special lining of modern skiing boots will not be affected. The drying process is based on a specifically developed, electronically driven, electrical heating system. Heating temperature is under 50°C, depends on room temperature.

Heating period
Heating time can be checked by timer. It is recommended to operate the heating overnight (off peak hours). Turn the shoe dryer on for 6 to 7 hours in the evening to dry and in the morning 30 minutes to preheat the shoes before putting them on.

Advice
Best results will be achieved by putting the boot on the heating element with toecap upturned.